

80/20 POLY COTTON **CONTI SUIT REFLECTIVE**



ВК

EG GY

KH

NB

RD

Description

Dromex® DW-CONTI-RT-S high visibility jacket and pants suit is a strong, lightweight and durable work garment designed to provide the user with protection against mechanical hazards such as abrasion.

The DW-CONTI suit is a blend of 80% polyester and 20 % cotton which is an affordable alternative to 100% cotton with the benefits of sturdiness and colour fastness of polyester and comfort of the cotton.

This garment is available in 8 different colours, royal blue, black, emeraldgreen, grey, khaki, navy blue, orange and red which consists of the

Jacket features:

- · Collared jacket.
- Concealed YKK metal zip closure.
- 2 Open laid on waist pockets and 1 left breast pocket with a V flap, concealed metal press stud closure with pen division and a Dromex®
- · High visibility lime green silver reflective tape on arms for enhanced visibility when working in poor lighting environments.
- Stress points are re-enforced with bar tacks for added durability.

Pants features:

- A concealed YKK metal zip with metal button closure at waist.
- Two fronts laid on pockets and a rear open pocket with a Dromex®
- Seams are triple needle top stitched and stress points are bar tacked for added durability.
- Inner elasticated waist for optimum fit and flexibility with 7 belt loops.
- High visibility lime green silver reflective tape on legs for enhanced visibility when working in poor lighting environments.

This garment is suitable for use in general work environments such as logistics, warehousing, construction, workshops, maintenance and repairs, janitorial, gardening and general-purpose applications.

Special Instructions

None of the materials or processes used in the manufacture of these products are known to be harmful to the wearer.

The manufacturer has examined under the system for ensuring quality of production by means of monitoring and inspection.

These polycotton garments are designed to accommodate the basic safety requirements and standards for Personal Protective Equipment. Not for use against heat and flame hazards.

The information contained herein is intended to assist the wearer in the selection of personal protective equipment.

Actual conditions of use cannot be directly simulated in a test environment therefore it is the responsibility of the end user and not the manufacturer or supplier to determine the garment suitability for the intended use.

This garment should be thoroughly inspected before use to ensure no damage is present.

Specifications

Style:

Fabric composition: Mass:

200gsm. Reflective:

50mm Lime silver reflective tape.

Long sleeve jacket and pants suit. 80% Polyester 20% Cotton.













Packaging, Storage & Obsolescence

Dromex® DW-CONTI-RT-S are packed in individual polybags and sold in the following quantities:

Royal Blue

- Size 30 48 = 20 per carton.
- Size 50 64 = 10 per carton.

Other colours

• Size 30 - 64 = 10 per carton.

Should there be visible damage such as tears, it is recommended to replace the garment immediately.

Cleaning & Maintenance

- The following suggestions will help keep your garment safe and neat:
- Polycotton garments can be cleaned by home cleaning or commercial laundering provided all the recommended conditions and setting are adhered to.
- Should home procedures not remove contaminants, then dry cleaning is recommended.
- Our recommended cleaning for these garments is as follows:
 - Pre-treat greasy stains and wash the garment in warm water with a light cleaning solvent.
 - Do not use Hypochlorite bleach or detergents containing Hypochlorite bleach.
 - Chlorine bleach may cause fading and reduce fabric strength.
 - Do not overload home laundry equipment.
 - Do not tumble dry garments.
 - Thoroughly rinse the garment to remove any wetting agents.
 - Do not hang in direct sun.
 - Sunlight can cause fading and reduce fabric strength.
 - Iron the garment to on low heat.
 - Do not iron on reflective tape.
 - When using commercial laundry aids, be sure to read and carefully follow the manufacturer's instructions.

Warm	Do not use	Do not	Cool Iron	Dry
Wash	Bleach	tumble dry		Cleana
30C	\times	\boxtimes	•	(P

Sizes Available

Jackets 30-64

Size	Nominal measurements of finished garment (cm)				
designation	Chest circumference	Back length ^b	Back width	Sleeve length	
30	92	64	41	43	
32	97	64.5	42.5	43	
34	102	65	45.05	43	
36	107	65.5	45.5	44	
38	112	68	47	45	
40	117	68,5	48.5	45	
42	122	69	50	45	
44	127	70,5	51.5	45	
46	132	72	53	46	
48	137	73,5	55	47	
50	142	75	56	48	
52	147	76,5	57.5	49	
54	152	77	59	49	
56	157	77,5	60.5	49	
58	162	78	62	50	
60	167	78,5	63.5	50	
62	172	79	65	50	
64	177	79.5	66.5	50	

Pants 26-60

Size	Nominal measurements of finished garment (cm)				
designation	Waist extended	Outside leg length	Inside leg length		
26	72	96.5	71.5		
28	77	97.5	72		
30	82	98.5	72.5		
32	87	100	73		
38	102	103.5	75		
40	107	105	75.5		
42	112	106	76.5		
44	117	107.5	77		
46	112	108.5	77.5		
48	127	110	78.5		
50	132	111	79		
52	137	112.5	80		
54	142	113.5	80.5		
56	152	114.5	81		
58	157	115.5	81.5		
60	162	116.5	82		

Marking/Labels

DROMEX



Position:

Jacket-Neck (inside) Pants-Inside (left pocket)

SIZE



Position: Jacket-Neck

Pants-Inside (left pocket)

SIDEWINDER



Position: Jacket-Top pocket Pants-Back (right pocket)

ORIGIN & YOM



Position:

Jacket-Top pocket Pants-Inside (left pocket)

Disposal

All industrial waste should be disposed of correctly according to local regulations and good disposal practice. Workwear should be disposed of considering the hazardous substance they were used for as well as the material they are made up of.

Please consider recycling.