

Dromex



DW-D59-BOILERSUIT



Description

Dromex® DW-D59MXX-O, 100% cotton high visibility boilersuit is designed to protect the user from basic hazards such as abrasion whilst being durable and hardwearing, commonly used in the mining, rigging and steel installation industries.

The Dromex® DW-D59MXX-O boilersuit is approved to the latest SAN 434 specification and has the SABS permit marking.

The Dromex® D59 100 % cotton fabric construction is breathable, preventing accumulation of sweat especially when working in hot and humid environments and being natural is hypoallergenic, reducing skin irritations whilst promoting comfort. This fabric also provides thermal insulation when working in cooler environments.



This attire consists of the following:

- High visibility silver reflective tape on the arms, front legs, front shoulders, above breast pockets and orange flame retardant reflective tape on back legs, back shoulders, arm and rear of jacket for enhanced visibility when working in poor lighting environments.
- Collared neck with hanger loop.
- Concealed two way zip with metal button closure.
- Seams are triple needed stitched for durability.
- 1 left pocket with a V- flap, 1 open rear pant pocket and 2 swing pockets.
- Cargo pocket on left leg of trouser features double needle topstitching with a V-flap and concealed press stud closure.
- Available in white, yellow and orange.

Special Instructions

None of the materials or processes used in the manufacture of these products are known to be harmful to the wearer. The manufacturer has examined under the system for ensuring quality of production by means of monitoring and inspection.

These workwear garments are designed to accommodate the basic safety requirements and standards for Personal Protective Equipment.

The information contained herein is intended to assist the wearer in the selection of personal protective equipment.

Actual conditions of use cannot be directly simulated in a test environment therefore it is the responsibility of the end user and not the manufacturer or supplier to determine the workwear suitability for the intended use.

Workwear protective garments should be thoroughly inspected before use to ensure no damage is present.

Specifications

Style:

One piece long sleeve boiler suit, with high visibility reflective tape in silver and flame retardant orange.

Fabric composition:

100% Cotton.

Mass:

270gsm.

Reflective:

50mm silver reflective tape (front of garment) and 50mm flame retardant orange reflective tape (back of garment).



Back of garment



Compliance & Conformity

- Garments comply to the latest SANS 434 standard (This standard specifies requirements for the material, cut, make and trim of boiler-suits, two-piece work wear suits, bib and brace overalls, coats and unlined jackets).

This standard makes reference to the following relevant standards:

- SANS 1362 Sewing threads.
- SANS 1387-4 Part 4: Cotton jean and drill fabrics.
- SANS 1387-10 Part 10: Pocketing.
- SANS 1822 Slide fasteners.
- SANS 5278 Sewing stitches per unit length.
- SANS 10235 Fibre-content labelling of textiles and textile products.
- SANS 50471 High-visibility warning clothing for professional use.
- The fabric is to SANS 1387-4 for D59 drill fabric, 4/1 satin weave @270gsm, 37 thread per cm weft and 19 threads per cm warp. The breaking strength is 940 N warp and 510 N weft.
- These products are manufactured in ISO9001:2008 (SANS9001) accredited manufacturing facilities and being mark bearing SABS garments are checked for conformity by the SABS.

Packaging, Storage & Obsolescence

DW-D59MXX-O, size 32 –64 is packed in an individual polybag and sold as 15 units

Should there be visible damage such as tears, it is recommended to replace the garment immediately.

Cleaning & Maintenance

The following suggestions will help keep your garment safe and neat:

- D59 garments can be cleaned by home cleaning or commercial laundering provided all the recommended conditions and setting are adhered to.
- Should home procedures not remove contaminants, then dry cleaning is recommended.
- Our recommended cleaning for these garments is as follows:
 - Pre-treat greasy stains and wash the garment in warm water with a light cleaning solvent.
 - Do not use Hypochlorite bleach or detergents containing Hypochlorite bleach.
 - Chlorine bleach may cause fading and reduce fabric strength.
 - Do not overload home laundry equipment.
 - Do not tumble dry garments.
 - Thoroughly rinse the garment to remove any wetting agents.
 - Do not hang in direct sun.
 - Sunlight can cause fading and reduce fabric strength.
 - When using commercial laundry aids, be sure to read and carefully follow the manufacturer's instructions.
 - Iron on low heat.
 - Do not iron on reflective tape.



Marking/ Labels

DROMEX

SIDEWINDER




Position:
Boilersuit-Neck (inside)

SIZE




Position:
Boilersuit-Top pocket

PRODUCT & YOM LABEL



Position:
Boilersuit-Neck

PRODUCT



Position:
Boilersuit-Neck



SANS 1387-4, SANS 434

Sizes Available

32-64

Size designation	Nominal measurements of finished garment (cm)										Back Width
	Circumference of					Length of					
	Chest	Waist (Extended)	Seat	Plain & Runched Cuff (Extended)	Bottoms	Back Neck to Wast	Outside Leg	Inside Leg	Set-in sleeves and raglan sleeves		
									Long Sleeve	Short Sleeve	
77	94	80	92	27	42	48	102	78	47	13	36
82	99	85	97	27	44	49	104	79	47	13	38
87	104	90	102	27	46	50	106	80	48	13	40
92	109	95	107	28	48	51	108	81	48	14	42
97	114	100	112	28	50	52	110	82	49	14	44
102	119	105	117	28	50	53	110	82	49	14	46
107	124	110	122	29	50	54	111	82	50	15	48
112	129	115	127	29	50	55	111	82	50	15	48
117	134	120	132	29	51	56	111	81	51	15	52
122	139	125	137	30	51	57	111	81	51	16	54
127	144	130	142	30	51	57	111	80	52	16	56
132	149	135	147	30	51	57	111	80	52	16	58
137	154	140	152	31	52	57	112	80	53	17	60
142	159	159	145	157	52	58	112	80	53	17	62
147	164	150	162	31	52	58	113	80	54	17	64
152	169	155	167	32	52	58	113	80	54	18	66
157	174	160	172	32	52	58	113	80	54	18	68
162	179	165	177	33	52	59	114	80	54	18	69.5
167	184	170	182	33	52	59	114	80	54	18	71